

MILLING MACHINES

GANTRY TYPE

GANTRY TYPE		FRUN-A 200-500	FRUN-B 200-800	FRUN-C 200-800
Working travel X- cross	(mm)	5000 ÷ 25000	5000 ÷ 25000	5000 ÷ 25000
Working travel Y- cross	(mm)	3600 ÷ 6600	3600 ÷ 9600	3600 ÷ 9600
Working travel Z- vertical	(mm)	1500 / 2000	1500 / 2000	1500 / 2000
Working travel W- cross rail	(mm)	-	-	-
Column to column distance	(mm)	3000 ÷ 6000	3000 ÷ 9000	4000 ÷ 9000
Clearance between table and cross-rail	(mm)	min. 2450	min. 2450	min. 2450
Motor output	(kW)	30 / 37 / 45	60 / 71	100 / 113

GANTRY TYPE		FRUF-A 250-500	FRUF-B 300-800	FRUF-C 300-800
Working travel X- cross	(mm)	5000 ÷ 25000	5000 ÷ 25000	5000 ÷ 25000
Working travel Y- cross	(mm)	4500 ÷ 7000	5200 ÷ 10200	5200 ÷ 10200
Working travel Z- vertical	(mm)	1500 / 2000	1500 / 2000	1500 / 2000
Working travel W- cross rail	(mm)	2000 / 2500	2500 / 3000	2800 / 3800 / 4800
Column to column distance	(mm)	3500 ÷ 6000	4000 ÷ 9000	4000 ÷ 9000
Clearance between table and cross-rail	(mm)	2800 ÷ 3550	3500 ÷ 4000	3500 ÷ 6500
Motor output	(kW)	30 / 37 / 45	60 / 71	100 / 113

